

Triple-S Chemical Products, Inc.



3464 Union Pacific Avenue
Los Angeles, CA 90023
www.patinas.com

Toll Free: (888) 417-5214
Tel: (323) 261-7301
Fax: (323) 261-5567

SILVER LOOK **For Copper, Brass and Bronze**

DESCRIPTION:

This is a unique formula designed to develop a pure **Silver Deposit** on Copper, Bronze, Brass or their alloys by immersion or rubbing. This solution is a non-Cyanide paste for the chemical silvering of different metals at room temperature. It is widely used on lighting fixtures, lamps, sculptures, hardware, gift items, and furniture. The surface will not chip, flake, or peel.

PREPARATION:

Parts must be free of grease, alkalinity or acid when **Silver Look** is applied. Parts must be thoroughly cleaned and deoxidized prior to blackening. **Cleaner 104** is recommended for removing heavy oils and oxidation. Do not use petroleum-degreasing solvents that leave a residue on the surface. Rinse thoroughly with over flowing cold water to remove residual cleaners and dust. It is important that alkaline cleaners are completely rinsed off prior to blackening.

IMPORTANT: Triple- S does **NOT** recommend using any sort of alcohol, solvent, acid or degreaser to clean parts prior to solution application. **Cleaner 104** is a great cleaner to ready parts for **Silver Look** or even powdered cleaners such as **Ajax** or **Comet** can also be used. Use the cleaner in conjunction with a scotch brite pad and apply medium strength scrubbing to prepare the part then thoroughly rinse with fresh water. **Cleaner 104** run off should be contained and disposed of as per local hazmat disposal laws.

DIRECTIONS:

Clean the parts with **Cleaner 104** (1 part of **Cleaner 104** with 2 parts of water). Rinse in water. Apply the **Silver Look** solution with a cloth or brush for 10 seconds; rubbing several times. If parts are originally bright, a pure Silvery deposit will develop. Rinse the parts with water or a sponge and wipe dry. If the parts are to be given Pewter look with dark areas, first darken the part in **Black C-22** or **Black C-1**, (according to their instructions, both products should be diluted with 5 parts of water before use, for 30 seconds to 1 minute) followed by a fresh water rinse and drying. Highlight the part with steel wood or steel brush or a buffing wheel. You can then apply Pewter paste on top of the highlighted area. Clean again and dry. Lacquer the parts using Triple-S **WSL-55** or **Trilac-747** or **AL-70**.

CAUTION:

Avoid contact with skin or eyes. Contact with skin or eyes may cause irritation and/or burning sensation. Protective clothing, rubber gloves and a face shield should be worn when handling.

Do not take internally!

FIRST AID:

In case of skin contact, wash skin with large amounts of fresh water. In case of eye contact flush immediately with large amount of fresh water for at least 15 minutes and **Call a Physician Immediately!**

DISPOSAL:

Contaminated product soil, water container residues and spill clean-up materials may be hazardous wastes. Avoid contact water. Comply with local, state and federal regulations concerning solid or hazardous waste disposal and or container disposal.